

Bulletin
80-06

April 9, 1982

Dockets 50-313
50-368

Arkansas Power and Light Company
ATTN: Mr. William Cavanaugh III
Senior Vice President - Energy Supply
Post Office Box 551
Little Rock, Arkansas 72203

Gentlemen:

This letter is to confirm the agreements reached between you and I and members of our respective staffs on April 8 and 9, 1982, concerning the adequacy of your response to IE Bulletin 80-06, "Engineered Safety Feature (ESF) Reset Controls," dated March 13, 1980. During our discussion in a meeting in the Region IV office on April 8, and in telephone discussions on April 9, you indicated that you would reevaluate the actions taken in response to IE Bulletin 80-06 to include:

- An engineering review of the electrical schematics for Unit 2 to identify all ESF components to be considered as required by IE Bulletin 80-06.
- Identification of ESF components which have not been tested as specified in Action Statement 2 of IE Bulletin 80-06.
- Evaluation of the safety implications of this failure to test. This safety evaluation would be documented and furnished to this office by April 16, 1982.
- Identification of any valves or other ESF components not modified as specified in IE Bulletin 80-06 and provision of your basis for not modifying them.
- Confirmation that testing was performed to verify the adequacy of modification for any valves or ESF components previously modified to conform to guidance of Action Statement 3 of IE Bulletin 80-06.
- Definition of testing and any additional modifications necessary to be fully responsive to the actions specified in IE Bulletin 80-06 by April 16, 1982, such that these activities may be accomplished at the earliest opportunity for Unit 2, but not later than resumption of operation following the next cold shutdown.

8205040406 820409
PDR ADOCK 05000313
Q PDR

RETURN RECEIPT REQUESTED

OFFICE	RPS-C	RPB2	DDRP&EP	EIS	DRA	RA-RIV	
SURNAME	REHall/nh	WCSeidle	JECagliardo	EHJohnson	KWeyfrit	JTCollins	
DATE	4/9/82	4/9/82	4/9/82	4/9/82	4/9/82	4/9/82	

April 9, 1982

- g. For Unit 1, evaluate the actions taken and correspondence previously furnished to the Nuclear Regulatory Commission to identify the need for additional corrective action or testing required as a result of the evaluations being performed for Unit 2.

You also indicated that if any problems are identified during your review of the schematics or performance of testing, which after your verification would alter the conclusions previously reported to the Nuclear Regulatory Commission relative to IE Bulletin 80-06, you would promptly report this matter to us for our evaluation.

If your understanding of your commitments described above is not in accordance with your actual plans or actions, please contact this office within 24 hours of your receipt of this letter by telephone (877) 465-8100.

Sincerely,

Original signed by
John T. Collins

John T. Collins
Regional Administrator

cc:
Arkansas Nuclear One
ATTN: James P. O'Hanlon
General Manager
Post Office Box 608
Russellville, Arkansas 72801

bcc to DMB for dist. _____

bcc dist. by RIV _____

BC
PM
AEOD
ELD
IE FILE
IE/RPRIB
NRC PDR

NRR/DHFS
NRR/OLB
RAD ASMT BR
RESEARCH
LPDR
NSIC
NTIS

RRI
Section Chief
Regional Administrator
Enforcement Assistant
Arkansas State Dept. of Health
G. Vissing, NRR
R. Martin, NRR

OFFICE							
SURNAME							
DATE							