

0 1 A L J M F 1 2 0 0 - 0 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5
7 8 9 14 15 25 26 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

REPORT SOURCE L 6 0 5 0 0 0 3 4 8 7 0 3 2 8 8 2 8 0 4 2 2 8 2 9
60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10

0 2 At 0850 on 3/28/82 while performing FNP-1-STP-201.19B (RCS TE-422B & TE-422D

0 3 Calibration and Functional Test), the Tavg-Low-Low "B" instrumentation loop was

0 4 declared inoperable as a result of an out of spec. indicator reading. Tech. Spec.

0 5 3.3.2.1, in part, requires this instrumentation loop to be operable. Tech. Spec.

0 6 3.3.2.1 action statement requirements were met. Health/Safety of the public was

0 7 not affected.

0 8

0 9

1 0

1 1

1 2

1 3

1 4

1 5

1 6

1 7

1 8

1 9

2 0

2 1

2 2

2 3

2 4

2 5

2 6

2 7

2 8

2 9

3 0

3 1

3 2

3 3

3 4

3 5

3 6

3 7

3 8

3 9

4 0

4 1

4 2

4 3

4 4

4 5

4 6

4 7

4 8

4 9

5 0

5 1

5 2

SYSTEM CODE I B 11 CAUSE CODE E 12 CAUSE SUBCODE G 13 COMPONENT CODE I N S T R U 14 COMP SUBCODE E 15 VALVE SUBCODE Z 16
EVENT YEAR 8 2 21 SEQUENTIAL REPORT NO. 0 1 4 24 OCCURRENCE CODE 0 3 28 REPORT TYPE L 30 REVISION NO. 0 32
ACTION TAKEN A 18 FUTURE ACTION Z 19 EFFECT ON PLANT Z 20 SHUTDOWN METHOD Z 21 HOURS 0 0 0 0 22 ATTACHMENT SUBMITTED N 23 NPRD-4 FORM SUB. N 24 PRIME COMP. SUPPLIER N 25 COMPONENT MANUFACTURER W 1 2 0 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27

1 0 This event is attributable to setpoint drift. The power supply card was replaced and

1 1 following the performance of FNP-1-STP-201.19B, the TE-422D instrumentation channel

1 2 was declared operable at 2125 on 3/28/82.

1 3

1 4

1 5

1 6

1 7

1 8

1 9

2 0

2 1

2 2

2 3

2 4

2 5

2 6

2 7

2 8

2 9

3 0

3 1

3 2

3 3

3 4

3 5

3 6

3 7

3 8

FACILITY STATUS E 28 % POWER 1 0 0 29 OTHER STATUS NA 30 METHOD OF DISCOVERY B 31 DISCOVERY DESCRIPTION Surveillance Test 32
ACTIVITY CONTENT RELEASED OF RELEASE Z 33 Z 34 AMOUNT OF ACTIVITY NA 35 LOCATION OF RELEASE NA 36
PERSONNEL EXPOSURES NUMBER 0 0 0 37 TYPE Z 38 DESCRIPTION NA 39
PERSONNEL INJURIES NUMBER 0 0 0 40 DESCRIPTION NA 41
LOSS OF OR DAMAGE TO FACILITY TYPE Z 42 DESCRIPTION NA 43
PUBLICITY ISSUED N 44 DESCRIPTION NA 45

NRC USE ONLY

NAME OF PREPARER W. G. Hairston, III

PHONE: (205) 899-5156

8205040413 820422

PDR ADDCK 05000348
S PDR