

CONTROL BLOCK:

--	--	--	--	--	--	--

 (1)

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

CON'T

0	1
---	---

REPORT SOURCE

L	6	0	5	0	0	0	2	6	3	7	0	4	1	0	8	2	8	0	4	2	3	8	2	9
---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---

60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 | During preparation for plant startup, inboard and outboard 18" drywell
0 3 | vent valves failed to close upon hand switch activation. Occurrence
0 4 | reportable under Technical Specification 6.7.B.1.i. Valves were opened
0 5 | following a reactor scram to deinert the drywell and were maintained
0 6 | in an open position for approximately 48 hours prior to attempting to
0 7 | close. No previous similar reportable events. No effect on public health
0 8 | or safety.

SYSTEM CODE S D		CAUSE CODE B		CAUSE SUBCODE C		COMPONENT CODE V A L V O P				COMP. SUBCODE D		VALVE SUBCODE Z			
EVENT YEAR 8 2		SEQUENTIAL REPORT NO. 0 0 4		OCCURRENCE CODE 0 1		REPORT TYPE T		REVISION NO. 0							
ACTION TAKEN A		FUTURE ACTION Z		EFFECT ON PLANT Z		SHUTDOWN METHOD Z		HOURS 0 0 0 0		ATTACHMENT SUBMITTED N		PRIME COMP. SUPPLIER A		COMPONENT MANUFACTURER A 6 4 0	

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 | Two ASCO 3 way Solenoid valves model 830064C64U, failed to vent when coil
1 1 | deenergized. Probable cause, solenoids mounted horizontally (which
1 2 | decrease opening force and increase friction) and possible residual core
1 3 | magnetism. All purge and vent valve solenoids replaced with new
1 4 | valves mounted vertical i.a.w. vendor instructions.

1 5 G 28 0 0 0 29 NA 30 A 31 Operator Observation 32

ACTIVITY CONTENT
RELEASED OF RELEASE

1 6 2 33 2 34 NA

7 8 9 10 11 44

AMOUNT OF ACTIVITY (35)

NA

LOCATION OF RELEASE (36)

PERSONNEL EXPOSURES

NUMBER		TYPE	DESCRIPTION
1	7	0 0 0 (37) Z (38)	NA (39)

PERSONNEL INJURIES		NUMBER		DESCRIPTION	
1	2	3	4	5	6
1	0	0	0	40	NA

1		2		3		4		5		6		7		8		9		10		11		12		13		14		15		16		17		18		19		20		21		22		23		24		25		26		27		28		29		30		31		32		33		34		35		36		37		38		39		40		41		42		43		44		45		46		47		48		49		50		51		52		53		54		55		56		57		58		59		60	
1		2		3		4		5		6		7		8		9		10		11		12		13		14		15		16		17		18		19		20		21		22		23		24		25		26		27		28		29		30		31		32		33		34		35		36		37		38		39		40		41		42		43		44		45		46		47		48		49		50		51		52		53		54		55		56		57		58		59		60	
1		2		3		4		5		6		7		8		9		10		11		12		13		14		15		16		17		18		19		20		21		22		23		24		25		26		27		28		29		30		31		32		33		34		35		36		37		38		39		40		41		42		43		44		45		46		47		48		49		50		51		52		53		54		55		56		57		58		59		60	
1		2		3		4		5		6		7		8		9		10		11		12		13		14		15		16		17		18		19		20		21		22		23		24		25		26		27		28		29		30		31		32		33		34		35		36		37		38		39		40		41		42		43		44		45		46		47		48		49		50		51		52		53		54		55		56		57		58		59		60	
1		2		3		4		5		6		7		8		9		10		11		12		13		14		15		16		17		18		19		20		21		22		23		24		25		26		27		28		29		30		31		32		33		34		35		36		37		38		39		40		41		42		43		44		45		46		47		48		49		50		51		52		53		54		55		56		57		58		59		60	
1		2		3		4		5		6		7		8		9		10		11		12		13		14		15		16		17		18		19		20		21		22		23		24		25		26		27		28		29		30		31		32		33		34		35		36		37		38		39		40		41		42		43		44		45		46		47		48		49		50		51		52		53		54		55		56		57		58		59		60	
1		2		3		4		5		6		7		8		9		10		11		12		13																																																																																															

8 9 10
PUBLICITY
ISSUED DESCRIPTION (45)
2 0 [N] (44) NA
NRC USE ONLY

NRC USE ONLY

A. V. Wojchowski

PHONE 612-295-5151

8205040494 820423
PDR ADOCK 05000263
S PDR