
50.55(e) Report





PUBLIC SERVICE COMPANY

P. O. BOX 21666 - PHOENIX, ARIZONA 85036

April 22, 1982 ANPP-20744-GHD/BSK

U. S. Nuclear Regulatory Commission Region V Creekside Oaks Office Park 1450 Maria Lane - Suite 210 Walnut Creek, California 94596-5368

Attention: Mr. T. W. Bishop, Chief

Reactor Construction and Engineering Support Branch

Subject: Time Extension for Report - DER 81-53

A 50.55(e) Potentially Reportable Deficiency Relating to Unit 1 Main Control Panel (JM-200) Violates Wiring

Separation Requirements

File: 82-019-026 D.4.33.2

Reference: (A) Telephone Conversation between J. Eckhardt and

G. Duckworth on December 30, 1981

(B) ANPP-20013, dated January 28, 1982 (Interim Report)

Dear Sir:

The NRC was notified of a potentially reportable deficiency in Reference (A) and an Interim Report was transmitted by Reference (B). At that time, it was estimated that a Final Report would be available by April 22, 1982.

Due to the extensive investigation and evaluation required, it is now expected that this information will be finalized by May 24, 1982, when a complete report will be submitted.

There is no change to the Interim Report at this time.

Very truly yours,

E. E. Van Brunt, Jr. APS Vice President Nuclear Projects ANPP Project Director

EEVBJr/GHD:skc

cc: See Attached Page 2

IE27

Cont

PR 29 PN 2:

U. S. Nuclear Regulatory Commission Attention: Mr. T. W. Bishop, Chief ANPP-20744-GHD/BSK April 22, 1982 Page 2

cc: Richard DeYoung, Director
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

J. A. Roedel

D. B. Fasnacht

G. C. Andognini

A. C. Rogers

B. S. Kaplan

W. E. Ide

J. Vorees

J. A. Brand

A. C. Gehr

W. J. Stubblefield

W. G. Bingham

R. L. Patterson

R. W. Welcher

R. M. Grant

D. R. Hawkinson

L. E. Vorderbrueggen

R. L. Greenfield Assistant Attorney General Bataan Memorial Building Santa Fe, New Mexico 87503

Ms. Patricia Lee Hourihan 6413 South 26th Street Phoenix, Arizona 85040