



April 23, 1982

Log No. K82-665

File: RR 2 (NP-33-82-22)

Docket No. 50-346

License No. NPF-3

Mr. James G. Keppler
Regional Administrator, Region III
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, Illinois 60137



Dear Mr. Keppler:

Reportable Occurrence 82-018
Davis-Besse Nuclear Power Station Unit 1
Date of Occurrence: March 26, 1982

Enclosed are three copies of Licensee Event Report 82-018 with supplemental information sheets which are being submitted in accordance with Technical Specification 6.9 to provide 30 day written notification of the subject occurrence.

Yours truly,

Terry D. Murray

Terry D. Murray
Station Superintendent
Davis-Besse Nuclear Power Station

TDM/ljk

Enclosure

cc: Mr. Richard DeYoung, Director
Office of Inspection and Enforcement
Encl: 30 copies

Mr. Norman Haller, Director
Office of Management and Program Analysis
Encl: 3 copies

Mr. Luis Reyes
NRC Resident Inspector
Encl: 1 copy

8205040762 820423
PDR ADDCK 05000346
S PDR

IE22
APR 28 1982