NRC	F	ORM	366	
(7.77	3			

U. S. NUCLEAR REGULATORY COMMISSION

CONTROL BLOCK (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION) (1) 034 01 0 0 1 (4) 0 1 N JS G S 0 0 0 0 -01 1 1 1 CON'T REPORT 2 7 0 4 1 0 8 2 (8) 0 4 8 8 0 1 LO 0 5 00 01 SOURCE REPORT DATE 61 DOCKET NUMBER EVENT DATE EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10) On April 10, 1982, during surveillance testing, the Control Room Operator discovered 0 2 that the service water flow to No. 12 Containment Fan Coil Unit (CFCU) was less 0 3 than the 700 GPM required. No. 12 CFCU was declared inoperable, and at 1211 hours, 0 4 Action Statement 3.6.2.3.a was entered. 0 0 6 0 80 SYSTEM CAUSE CAUSE COMP VALVE CODE COMPONENT CODE SUBCODE B (13) B E (12 L V E X (14 A (15 G (16) V A 19 18 OCCURRENCE REVISION SEQUENTIAL REPORT REPORT NO. CODE TYPE EVENT YEAR NC LER RO REPORT 13 0 0 L 0 2 4 NUMBER 28 30 COMPONENT TAKEN FUTURE EFFECT ON PLANT METHOD ATTACHMENT NPRD-4 PRIME COMP. HOURS (22) N (25) 0 (26) Y F 0 0 (23) 1 31 (21) 0 0 (24) 18) (19 CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27) Flow Control Valve 12SW223 had stuck in the closed position, resulting in low 1 0 service water flow to the CFCU. Valve 125W223 was exercised, and No. 12 CFCU was satisfactorily tested. The unit was declared operable, and at 1540 hours, 1 2 April 10, 1982, Action Statement 3.6.2.3.a was terminated. The failure of service 4 water SW223 valves is presently being investigated. A Supplemental Report will be <sup>9</sup> submitted upon completion. 80 METHOD OF OTHER STATUS (30) % POWER DISCOVERY DESCRIPTION (32) DISCOVERY 5 C (28) 0 0 29 N/A B (31) Surveillance Testing 9 10 ACTIVITY CONTENT 4.4 45 80 AMOUNT OF ACTIVITY (35 LOCATION OF RELEASE (36) RELEASED OF RELEASE 6 Z 33 Z 34 N/A N/A 10 80 PERSONNEL EXPOSURES DESCRIPTION (39) NUMBER TYPE 0 0 0 Z (38) N/A 80 PERSONNEL INJURIES DESCRIPTION (41) NUMBER 0 0 0 (40) N/A 80 LOSS OF OR DAMAGE TO FACILITY (43 YPE DESCRIPTION Z (42) N/A 80 PUBLICITY 8205110487 820428 NRC USE ONLY DESCRIPTION (45) PDR SSUED. N (44) ADOCK 05000272 PDR 68 69 609-935-0998 Frahm NAME OF PREPARER \_\_ R. PHONE .\_

LICENSEE EVENT REPORT