DCS MS-016

Docket No. 50-285

Mr. W. C. Jones Division Manager, Production Operations Omaha Public Power District 1623 Harney Street Omaha, Nebraska 68102

Dear Mr. Jones:

NRC PDR L PDR NSIC ORB#3 Rdg DEisenhut JHeltemes RAClark PMKreutzer-3 ETourigny OELD I&E ACRS-10 Gray File DVerrelli GRequa

DISTRIBUTION:



SUBJECT: NUREG-0737 ITEM III.D.3.3, IMPROVED IN-PLANT IOPINE INSTRUMENTATION UNDER ACCIDENT CONDITION

NUREG-0737 Item III.0.3.3 requires each licensee to improve in-plant indine instrumentation under accident conditions. We only reviewed deviations to the stated positions of NUREG-0737.

Based on our review of your submittals, no technical deviations from our stated positions were requested. Therefore, we interpret this to mean that you meet the position, and no further review by NRR is planned. If this understanding is not correct, we request formal notification of such, within 30 days of the date of this letter.

Sincerely, Original signed by Robert A. Clark

Robert A. Clark, Chief Operating Reactors Branch #3 Division of Licensing

cc: See next page

8205190431p

OFFICE) SURNAME	ORB#3: DL Ed) 6 i gny/pr 4/27/82	ORB#1#DL GReggea 4/9//82	ORB#3:DL RAClark 2. 2 4/27/82		

Omaha Public Power District

cc:

Marilyn T. Shaw, Esq. LeBoeuf, Lamb, Leiby & MacRae 1333 New Hampshire Avenue, N.W. Washington, D. C. 20036

Mr. Jack Jensen Chairman, Washington County Board of Supervisors Blair, Nebraska 68023

U.S. Environmental Protection Agency Region VII ATTN: Regional Radiation Representative 324 East 11th Street Kansas City, Missouri 64106

Mr. Frank Gibson W. Dale Clark Library 215 South 15th Street Omaha, Nebraska 68102

Alan H. Kirshen, Esq. Fellman, Ramsey & Kirshen 1166 Woodmen Tower Omaha, Nebraska 68102

Mr. Larry Yandell U.S.N.R.C. Resident Inspector P. O. Box 309 Fort Calhoun, Nebraska 68023

Mr. Charles B. Brinkman
Manager - Washington Nuclear
Operations
C-E Power Systems
Combustion Engineering, Inc.
4853 Cordell Avenue, Suite A-1
Bethesda, Maryland 20014

Regional Administrator Nuclear Regulatory Commission, Region IV Office of Executive Director for Operations 611 Ryan Plaza Drive Suite 1000 Arlington, Texas 76011