TENNESSEE VALLEY ALTHORITY CHATTANOOGA, TENNESSEE BA400 EORGIA 1750 Chestnut Street Tower II 82 APR 29 A 5 . 46

April 27, 1982

Mr. James P. O'Reilly, Director U.S. Nuclear Regulatory Commission Office of Inspection and Enforcement Region II 101 Marietta Street, Suite 3100 Atlanta, Georgia 30303

Dear Mr. O'Reilly:

TENNESSEE VALLL AUTHORITY - BROWNS FERRY NUCLEAR PLANT UNIT 3 - DOCKET NO. 50-296 - FACILITY OPERATING LICENSE DPR-68 - REPORTABLE OCCURRENCE REPORT BFRO-50-296/82011

The enclosed report provides details concerning reactor protection system water level switches which were found with setpoints outside technical specification limits. This report is submitted in accordance with Browns Ferry unit 3 Technical Specification 6.7.2.a(5).

Very truly yours,

TENNESSEE VALLEY AUTHORITY

Director of Nuclear Power

Enclosure

cc (Enclosure):

Document Control Desk U.S. Nuclear Regulatory Commission Washington, DC 20555

Records Center Institute of Nuclear Power Operations 1820 Water Place Atlanta, Georgia 30339

NRC Inspector, Browns Ferry

IE 22