

General Offices: 1945 West Parnall Road, Jackson, MI 49201 • (517) 788-0550

May 19, 1982

James G Keppler, Administrator Region III US Nuclear Regulatory Commission 799 Roosevelt Road Glen Ellyn, IL 60137

DOCKET 50-255 - LICENSE DPR-20
PALISADES PLANT - LICENSEE EVENT REPORT 82-14
EXCESSIVE LEAKAGE THROUGH ESCAPE LOCK INNER DOOR

Attached is Licensee Event Report (LER) 82-14 (Excessive Leakage Through Escape Lock Inner Door), which is reportable under Technical Specification 6.9.2.A(3).

Brian D Johnson

Senior Licensing Engineer

Brian D Thurson

CC Director, Office of Nuclear Reactor Regulation Director, Office of Inspection and Enforcement NRC Resident Inspector - Palisades

Attachment - 1 Page

MAY 2 1 1982

IE22