

CONTROL BLOCK:

--	--	--	--	--	--

 ① (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

CONTROL BLOCK:										(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)									
C O F I S V I										L I C E N S E N U M B E R									
L I C E N S E E C O D E										L I C E N S E T Y P E									
R E P O R T S O U R C E										D O C K E T N U M B E R									
E V E N T D E S C R I P T I O N A N D P R O B A B L E C O N S E Q U E N C E S																			
With the reactor operating at power between April 17, 1982, and April 26, 1982, only one complete prestressed concrete reactor vessel (PCRV) liner cooling loop was operating on several occasions. The subheaders of Loop 1 were isolated one at a time, each for less than 48 hours, to locate a primary coolant to PCRV liner cooling system leak. This constituted a degraded mode of LCO 4.2.13 and is reportable per AC 7.5.2(b)2 and AC 7.5.2(b)4 of the Technical Specifications. No effect on public health or safety. Similar report: 80-37.																			
S Y S T E M C O D E										C A U S E C O D E									
C A U S E S U B C O D E										C O M P O N E N T C O D E									
V A L V E S U B C O D E										R E V I S I O N N O .									
L E R / R O R E P O R T N U M B E R										E V E N T Y E A R									
A C T I O N T A K E N										F U T U R E A C T I O N									
E F F E C T O N P L A N T										S H U T D O W N M E T H O D									
H O U R S										A T T A C H M E N T S U B M I T T E D									
N P R D - 4 F O R M S U B										P R I M E C O M P S U P P L I E R									
C O M P O N E N T M A N U F A C T U R E R																			
C A U S E D E S C R I P T I O N A N D C O R R E C T I V E A C T I O N S																			
A leakage path through the core support floor liner and into the faulty cooling tube existed. The extent and cause of the cooling tube failure is unknown due to inaccessibility. The affected tube was capped on both the inlet and outlet and removed from service. A modification allows for monitoring for any future leakage from the isolated tube. No further corrective action is required or anticipated.																			
F A C I L I T Y S T A T U S										% P O W E R									
O T H E R S T A T U S										M E T H O D O F D I S C O V E R Y									
D I S C O V E R Y D E S C R I P T I O N																			
A C T I V I T Y C O N T E N T										A M O U N T O F A C T I V I T Y									
L O C A T I O N O F R E L E A S E																			
P E R S O N N E L E X P O S U R E S										P E R S O N N E L I N J U R I E S									
L O S S O F O R D A M A G E T O F A C I L I T Y										P U B L I C I T Y									
I S S U E D D E S C R I P T I O N																			
N A M E O F P R E P A R E R										P H O N E									