

TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401

1750 Chestnut Street Tower II

NRC REGION II
ATLANTA, GEORGIA

May 4, 1982

82 MAY 7 P 1: 31

Mr. James P. O'Reilly, Director
U.S. Nuclear Regulatory Commission
Office of Inspection and Enforcement
Region II
101 Marietta Street, Suite 3100
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

TENNESSEE VALLEY AUTHORITY - BROWNS FERRY NUCLEAR PLANT UNIT 1 - DOCKET
NO. 50-259 - FACILITY OPERATING LICENSE DPR-33 - REPORTABLE OCCURRENCE
REPORT BFRO-50-259/80011 REVISION 4

The enclosed report is a supplement to J. R. Calhoun's letters to you dated February 14, 1980, April 18, 1980, and June 9, 1980, and my letter to you dated October 13, 1981, concerning analysis of the containment purge and venting system by the Division of Engineering Design which has indicated a potential loss of secondary containment should primary containment purging be conducted during hot standby or power operations concurrent with a loss-of-coolant accident. This report is submitted in accordance with Browns Ferry unit 1 Technical Specification 6.7.2.A.9.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

J. A. Green
H. J. Green
Director of Nuclear Power

Enclosure

cc (Enclosure):

Document Control Desk
U.S. Nuclear Regulatory Commission
Washington, DC 20555

Records Center
Institute of Nuclear Power Operations
1820 Water Place
Atlanta, Georgia 30339

NRC Inspector, Browns Ferry

8206010155
S

OFFICIAL COPY
LE 22
S/P/P