

CONTROL BLOCK:

--	--	--	--	--	--	--

 ①

7	0	1	8	9	N	Y	J	A	F	1	14	2	0	0	-	0	0	0	0	-	0	0	0	25	3	4	1	1	1	1	30	4			57	CAT	58	5
				LICENSEE CODE										LICENSE NUMBER										LICENSE TYPE														

REPORT SOURCE L 6 0 5 0 0 0 3 3 3 7 0 4 2 3 8 2 8 0 5 2 0 8 2 9
60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

0 2 | During normal operation, control rod 26-51 could not be selected for movement and
0 3 | thus could not be normally inserted or withdrawn. Recent NRC interpretation of this
0 4 | problem results in the control rod being administratively considered inoperable as
0 5 | described by TS 3.3.A.2.a. Scram capability of the control rod was not effected.
0 6 | No hazard existed.

0	7		
0	8		

09		SYSTEM CODE R B		CAUSE CODE E		CAUSE SUBCODE A		COMPONENT CODE E L E C T R O N				COMP. SUBCODE Z		VALVE SUBCODE Z	
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22
17		EVENT YEAR 8 2		SEQUENTIAL REPORT NO. 0 1 9		OCCURRENCE CODE 0 3		REPORT TYPE L		REVISION NO. 0		ACTION TAKEN B		FUTURE ACTION Z	
23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38
EFFECT ON PLANT Z		SHUTDOWN METHOD Z		HOURS 0 0 0 0		ATTACHMENT SUBMITTED N		NPRO-4 FORM SUB. Y		PRIME COMP. SUPPLIER N		COMPONENT MANUFACTURER G 0 8 0		26	
39	40	41	42	43	44	45	46	47	48	49	50	51	52	53	54

1 0 | A broken wire on select switch 26-5i was the cause. Following repair, the control rod

1 1 | could be selected and was declared operable later the same day.

1	2	
---	---	--

1	3	
---	---	--

1	4	
---	---	--

FACILITY STATUS			% POWER			OTHER STATUS			METHOD OF DISCOVERY			DISCOVERY DESCRIPTION		
1	5	E	1	0	0	NA			A	Operator Observation				

ACTIVITY CONTENT
RELEASED OF RELEASE

1 6 33 34

7 8 9 10 11

AMOUNT OF ACTIVITY (35)

NA

44

LOCATION OF RELEASE (36)

NA

45 80

PERSONNEL EXPOSURES									
NUMBER			TYPE		DESCRIPTION				
1	7	0	0	0	(37)	Z	(38)	NA	(39)

PERSONNEL INJURIES NUMBER	DESCRIPTION
41	

1	8	0	0	0	(40)	NA				80	
7	8	9	11	12							
LOSS OF OR DAMAGE TO FACILITY					(42)						

TYPE		DESCRIPTION
1	9	NA

PUBLICITY
 ISSUED DESCRIPTION (45)
 2 0 N (44) NA
 8206010459
 NRC USE ONLY

(315) 342-3840 X207