

50-443

# HARMON & WEISS

1725 I STREET, N.W.

SUITE 506

WASHINGTON, D. C. 20006

GAIL MCGREEVY HARMON  
ELLYN R. WEISS  
WILLIAM S. JORDAN, III  
LEE L. BISHOP  
DIANE CURRAN  
LYNNE BERNABEI  
LUCIA S. ORTH

TELEPHONE  
(202) 833-9070

OF COUNSEL  
L. THOMAS GALLOWAY

June 1, 1982

Mr. Frank J. Miraglia  
Chief, Licensing Branch No. 3  
Office of Nuclear Reactor Regulation  
U.S. Nuclear Regulatory Commission  
Washington, D.C. 20555


Dear Mr. Miraglia:

On behalf of the New England Coalition on Nuclear Pollution, an intervenor in the Seabrook operating licensing proceeding, I am seeking information on the relevance of several NRC IE notices to the Seabrook facility. In doing so, I have been referred to your office by Mr. Roy Lessy, counsel for the NRC Staff in the Seabrook licensing proceeding. I would appreciate as prompt a reply as possible, as your answers will be helpful in determining whether to file contentions on these issues, for which the filing period is limited. My questions are the following:

1. Does IE Information Notice No. 82-13, re: "Failures of General Electric Type HFA Relays," apply to the Seabrook facility? If so, in what areas of the reactor are LEXAN or NYLON coil spools used?
2. Does IE Information Notice No. 82-14, re: "TMI-1 Steam Generator/Reactor Coolant System Chemistry/Corrosion Problem," apply to the Seabrook facility? If so, how?
3. Does IE Bulletin No. 81-03, re: "Flow Blockage of Cooling Water to Safety System Components by Corbicula sp. and Mytilus sp.," apply to the Seabrook facility? If so, how?

Thank you for your assistance in this matter.

Sincerely,



Diane Curran

YE03  
1/0

DC:sq

cc: Roy P. Lessy

8206030090 820601  
PDR ADDCK 05000443  
Q PDR