

DUKE POWER COMPANY

POWER BUILDING

422 SOUTH CHURCH STREET, CHARLOTTE, N. C. 28242

May 24, 1982

WILLIAM O. PARKER, JR.  
VICE PRESIDENT  
STEAM PRODUCTION

TELEPHONE: AREA 704  
373-4083

USNRC REGIONAL  
ATLANTA, GEORGIA  
02 JUN 2 4 8.33


Mr. James P. O'Reilly, Regional Administrator  
U. S. Nuclear Regulatory Commission  
Region II  
101 Marietta Street, Suite 3100  
Atlanta, Georgia 30303

Re: McGuire Nuclear Station Unit 1  
Docket No. 50-369

Dear Mr. O'Reilly:

Reportable Occurrence Report RO-369/82-33 was to have been submitted by May 24, 1982. This 30 day reportable occurrence (per T.S.6.9.1.13) concerns T.S.3.1.1.4, "The Reactor Coolant System lowest operating loop temperature ( $T_{avg}$ ) shall be greater than or equal to 551°F", which was violated on April 24, 1982. At this time investigation of the incident is not yet complete. The report will be submitted by June 4, 1982.

Very truly yours,



William O. Parker, Jr.

PBN/jfw

cc: Director  
Office of Management and Program Analysis  
U. S. Nuclear Regulatory Commission  
Washington, D. C. 20555

Records Center  
Institute of Nuclear Power Operations  
1820 Water Place  
Atlanta, Georgia 30339

Mr. P. R. Bemis  
Senior Resident Inspector  
McGuire Nuclear Station

OFFICIAL COPY

IE 22  
1/0

8206070333 820524  
PDR ADOCK 05000369  
S PDR