

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 9		SYSTEM CODE 1 B		CAUSE CODE D		CAUSE SUBCODE Z		COMPONENT CODE Z Z Z Z Z Z						COMP. SUBCODE Z		VALVE SUBCODE Z								
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22									
LER/RO REPORT NUMBER		EVENT YEAR 8 2		SEQUENTIAL REPORT NO. 0 1 6		OCCURRENCE CODE 0 1		REPORT TYPE L		REVISION NO. 0														
23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43	44	45	46	47
ACTION TAKEN H		FUTURE ACTION Z		EFFECT ON PLANT Z		SHUTDOWN METHOD Z		HOURS 0 0 0 0		ATTACHMENT SUBMITTED Y		NPRD-4 FORM SUB. M		PRIME COMP. SUPPLIER Z		COMPONENT MANUFACTURER Z 9 9 9								

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

PUBLICITY
 ISSUED DESCRIPTION (45)
 2 0 N 44 NA
 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

PHONE: 714/492-7700