LICENSEE EVENT REPORT

LICENSEE EVENT REPORT
CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)
0 1 N C B E P 1 2 0 0 - 0 0 0 0 - 0 0 3 4 1 1 1 1 1 4 5 5 5 EIGENSEE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 57 CAT 58
EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10 During plant operation, routine surveillance revealed that reactor pressure indicator
[0]3 [1-C32-PI-3332, located on the remote shutdown panel, showed 1,030 psi while actual
[0 4] pressure was 1,000 psi. The indicator was then declared inoperable in accordance with
[0] technical specifications. This event did not affect the health and safety of the
[0]6 [public.
07
Technical Specifications 3.3.5.2, 6.9.1.9b
SYSTEM CAUSE SUBCODE S
SEQUENTIAL REPORT NO. The point of the po
ACTION FUTURE ON PLANT METHOD HOURS 22 ATTACHMENT SUBMITTED FORM SUB SUPPLIER NANUFACTURER R 3 6 9 26 CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27
[1] A calibration check determination that the indicator was out of tolerance, combined
[1] [with a failed indicator conversion registor, R5, caused this event. The indicator,
[1] [Model No. 1151, and the conversion resistor were replaced in accordance with the
manufacturer's recommendations and the indicator was returned to service. As plant
[1]4 documentation shows this event is isolated, no further corrective action is planned.
FACILITY STATUS 30 METHOD OF DISCOVERY DESCRIPTION 32 1 5 E (28) 0 9 9 (29) NA A A DESCRIPTION 32
7 8 9 10 12 13 44 45 46 80 RELEASED OF RELEASE AMOUNT OF ACTIVITY 35 NA
PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION (39) 1 7 0 0 0 (37) Z (38) NA
1 8 9 PERSONNEL INJURIES NUMBER DESCRIPTION 41 NA
Z 8 9 11 12 80 LOSS OF OR DAMAGE TO FACILITY 43 TYPE DESCRIPTION NA
1 9 Z 42 NA NA 80
PUBLICITY 820329 NRC USE ONLY PDR ADDCK 05000325 PDR P
M. J. Pastva, Jr. (919) 457-9521