## TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401 1750 Chestnut Street Tower II

2 APR 5 All . 04

April 1, 1982

Mr. James P. O'Reilly, Director U.S. Nuclear Regulatory Commission Office of Inspection and Enforcement Region II 101 Marietta Street, Suite 3100 Atlanta, Georgia 30303

Dear Mr. O'Reilly:

TENNESSEE VALLEY AUTHORITY - SEQUOYAH NUCLEAR PLANT UNIT 1 - DOCKET NO. 50-327 - FACILITY OPERATING LICENSE DPR-77 - REPORTABLE OCCURRENCE REPORT SQRO-50-327/82034

The enclosed report provides details concerning the outlet flow balancing valve, 1-HCV-67-537B, for containment spray heat exchanger 1B being discovered closed and tagged with a hold order clearance that was previously signed off as complete. This report is submitted in accordance with Sequoyah unit 1 Technical Specification 6.9.1.13.c.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

Director of Nuclear Power

Enclosure

cc (Enclosure):

Document Control Desk U.S. Nuclear Regulatory Commission Washington, DC 20555

Records Center Institute of Nuclear Power Operations 1820 Water Place Atlanta, Georgia 30339

NRC Inspector, Sequoyah

B204160410 B20401 PDR ADDCK 0500032

DEFICIAL COPY