Memorandum

TO

Eber R. Price, Director

Division of State and Licensee Relations

FROM

L Kornblith, Jr., Assistant Director

Mfor Reactors

Division of Compliance

SUBJECT:

U. S. ARMY MATERIALS RESEARCH AGENCY

DOCKET NO. 50-47

ATTN: R. G. Page

The attached report by our field inspector of a visit to the Watertown Arsenal Reactor on April 1, 1965, is forwarded for information. No items of noncompliance or safety problems were noted during the visit.

The problem noted in our previous report regarding neutron multiplication during approach to critical has been resolved. A change in the beryllium reflector geometry resulted in the improvement in the observed mulitplication during a startup.

Attachment:

CO Rpt No. 47/65-1 by J. R. Sears dtd 6/18/65

Distribution:

J. P. O'Reilly, Region I (2)

M. L. Ernst, Region II

H. D. Thornburg, Region III

J. W. Flora, Region IV

R. H. Engelken, Tagion V

J. B. Sears, Region I

M. M. Mann, REG, w/o att.

C. A. Nelson, INS, w/o att.

R. L. Doan, DRL

E. G. Case, DRL

R. S. Boyd, DRL (2)

D. J. Skovholt, DRL

DRL Files



8204210376 811005 PDR FOIA KABAT-Z81-311 PDR persulain Qui in Cy inice