A

Memorandum

TO

Eber R. Price, Assistant Director Division of Licensing and Regulation

DATE: SEP 1 1 1963

FROM

SUBJECT:

L. Kornblith, Jr., Assistant Director for Reactors

Division of Compliance

U. S. ARMY MATERIAL RESEARCH AGENCY

DOCKET NO. 50-47

ATTN: R. G. Page (3)

Attached is a report by our field inspector of a visit to the subject facility on July 22-23, 1963. No items of noncompliance were observed during this visit.

You will note from the report that the licensee at this facility relies on administrative control to prevent fission chamber movement during control rod withdrawal. We are of the opinion that consideration should be given to the use of an interlock in this case.

Attachment:

Rpt by J. R. Sears dtd 8-15-63

Distribution:

J. R. Sears, Region I (2)

M. L. Ernst, Region II (2)

H. D. Thornburg, Region III

J. W. Flora, Region IV

R. H. Engelken, Region V

C. A. Nelson, INS, w/o attach.

LR File Room

8204210515 811005 PDR FOIA KABAT-Z81-311 PDR