



UNITED STATES
ATOMIC ENERGY COMMISSION
DIVISION OF COMPLIANCE
REGION I
970 BROAD STREET
NEWARK, NEW JERSEY 07102

201 845 3962

May 6, 1971

R. T. Carlson, Senior Reactor Inspector
Region I, Division of Compliance

U. S. ARMY MATERIALS & MECHANICS RESEARCH CENTER
CO REPORT NO. 47/71-1

Most of my pertinent comments are made in the Management Interview. As the facility has been deactivated, we might as well handle items of noncompliance other than the missing liquid effluent records by a no reply required 592.

Mr. O'Connor had an interesting comment that he didn't think it was a good idea to have a reactor licensed for an extended period of time after the personnel involved had become aware that the facility was to be shut down.

I'd suggest that we go back to the facility within a year and then, if there are no problems or changes, extending the interval between inspections to as long as possible.

J. P. Stohr
J. P. Stohr
Radiation Specialist