

April 16, 1982

Mr. J. G. Keppler, Regional Administrator Office of Inspection and Enforcement, Region III U. S. NUCLEAR REGULATORY COMMISSION 799 Roosevelt Road Glen Ellyn, Illinois 60137

Dear Mr. Keppler:

DOCKET 50-266
LICENSEE EVENT REPORT 82-007/01T-0
POINT BEACH NUCLEAR PLANT, UNIT 1

Enclosed is Licensee Event Report 82-007/01T-0

(a 14-day follow-up report) with an attachment which provides
a description of an event reportable in accordance with
Technical Specification 15.6.9.2.A.3, "Abnormal degradation
discovered in fuel cladding, reactor coolant pressure boundary,
or primary containment."

Very truly yours,

Assistant Vice President

C. W. Fay

Enclosure

Copies to NRC Resident Inspector Mr. Peter Anderson - WED

> APR 19 1982 IE22:/

8204220390 820416 PDR ADDCK 05000266 S PDR