

LICENSEE EVENT REPORT

CONTROL BLOCK:

--	--	--	--	--	--	--

 (1)

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 2 3 4 5 6 7 8 9
N Y I P S Z 0 0 - 0 0 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5
7 8 9 14 15 25 26 30 37 38 39
LICENSEE CODE LICENSE NUMBER LICENSE TYPE CAT 58

CON'T

0 1 2 3 4 5 6 7 8 9
REPORT SOURCE L 0 5 0 0 0 2 4 7 7 0 3 0 9 8 2 8 0 4 0 8 8 2 9
60 61 68 69 74 75 80
DOCKET NUMBER EVENT DATE REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 | During normal operation, Boron Injection Tank (Tech. Spec. 3.3.A) Level Channel 944E
0 3 | signal drifted down to 48% level. A plant shutdown was initiated in parallel with
0 4 | efforts to repair the Channel. Following repairs the plant shutdown was halted.
0 5 | There were no adverse effects on the public's health and safety since two redundant
0 6 | Channels remained functional.
0 7 |
0 8 |

SYSTEM CODE S F 11		CAUSE CODE E 12		CAUSE SUBCODE X 13		COMPONENT CODE I N S T R U 14			COMP. SUBCODE T 15		VALVE SUBCODE Z 16						
LER/RO REPORT NUMBER 17		EVENT YEAR 8 2		SEQUENTIAL REPORT NO. 0 1 2		OCCURRENCE CODE 0 3		REPORT TYPE L		REVISION NO. 0							
ACTION TAKEN X 18		FUTURE ACTION X 19		EFFECT ON PLANT B 20		SHUTDOWN METHOD Z 21		HOURS 0 0 0 1 22		ATTACHMENT SUBMITTED N 23		NPRD-4 FORM SUB. N 24		PRIME COMP. SUPPLIER X 25		COMPONENT MANUFACTURER B 0 8 0 26	

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 Solidification of boric acid in instrument impulse line resulted in erroneous
1 1 indication of level. The affected impulse line was cleared and the Channel
1 2 returned to service. (Transmitter Spec: Barton Electronic Transmitter, Model
1 3 232/252, DWG. CP-1254L9.12)
1 4

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60

FACILITY STATUS (1) 5 (E) (28) % POWER (1) 0 0 (29) OTHER STATUS (30) NA METHOD OF DISCOVERY (A) (31) DISCOVERY DESCRIPTION (32) Operator Observation

ACTIVITY CONTENT RELEASED OF RELEASE (1) 6 (Z) (33) (Z) (34) AMOUNT OF ACTIVITY (35) NA LOCATION OF RELEASE (36) NA

PERSONNEL EXPOSURES									
NUMBER			TYPE	DESCRIPTION					
1	7	0	0	0	(37)	Z	(38)	NA	(39)

PERSONNEL INJURIES										
NUMBER				DESCRIPTION						
1	8	0	0	0	40	NA				

LOSS OF OR DAMAGE TO FACILITY					
TYPE		DESCRIPTION			
1	9	Z	(42)	NA	

PUBLICITY
 ISSUED (2) (0) (N) (44) (45) NA
 82042607
 NRC USE ONLY

NAME OF PREPARER Malcolm C. Smith

PHONE: ~~(914) 526-5349~~