



UNITED STATES
NUCLEAR REGULATORY COMMISSION
REGION IV
611 RYAN PLAZA DRIVE, SUITE 1000
ARLINGTON, TEXAS 76011

Enclosure 2.

January 21, 1982

MEMORANDUM FOR: Ed Jordan, Director, Division of Engineering and
Quality Assurance, IE

FROM: John T. Collins, Regional Administrator, Region IV

SUBJECT: HAYWARD TYLER PUMP COMPANY

As a follow up to our phone conversation on Wednesday, January 20, 1982, I have enclosed a listing of pumps manufactured by Hayward Tyler Pump Company for the period 1977-1981. Note that two operating facilities, Salem 1 & 2 ✓ and Ocone, have received pumps from this company during this period and that the pumps were for non-safety systems. From our conversation, it is my understanding that you will discuss with Bob Bernero some type of risk analysis, particularly for those pumps installed in operating facilities. Please keep me advised as to your progress in this regard.

John T. Collins
John T. Collins
Regional Administrator

Enclosure:
As stated

cc: w/o encl.
R. DeYoung, IE
V. Stello, DEDROGR
K. Seyfrit, RIV
✓ U. Potapovs, RIV

8207010431 820325
PDR FOIA
HATTON82-121 PDR