

TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401
1750 Chestnut Street Tower II

RECEIVED
NRC REGIONAL
OFFICE
ATLANTA, GEORGIA
JUL 6 1982

July 1, 1982

Mr. James P. O'Reilly, Director
U.S. Nuclear Regulatory Commission
Office of Inspection and Enforcement
Region II
101 Marietta Street, Suite 3100
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

TENNESSEE VALLEY AUTHORITY - BROWNS FERRY NUCLEAR PLANT UNIT 2 - DOCKET
NO. 50-260 - FACILITY OPERATING LICENSE DPR-52 - REPORTABLE OCCURRENCE
REPORT BFRO-50-260/81069 - REVISION 1

The enclosed report is a supplement to my letter to you dated January 29,
1982 concerning scram discharge level switch 2-LS-85-45E (25-gallon rod
block) which was found to be inoperable. This report is submitted in
accordance with NRC Bulletin 80-14.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

J. A. Green
H. J. Green
Director of Nuclear Power

Enclosure

cc (Enclosure):

Document Control Desk
U.S. Nuclear Regulatory Commission
Washington, DC 20555

Records Center
Institute of Nuclear Power Operations
1820 Water Place
Atlanta, Georgia 30339

NRC Inspector, Browns Ferry

B207090252 B20701
PDR ADOCK 05000260
S PDR

OFFICIAL COPY

TE 22