

USNRC  
ATLANTA  
82  
JUL 12 4 31  
DUKE POWER COMPANY

POWER BUILDING  
422 SOUTH CHURCH STREET, CHARLOTTE, N. C. 28242

WILLIAM O. PARKER, JR.  
VICE PRESIDENT  
STEAM PRODUCTION

July 6, 1982

TELEPHONE: AREA 704  
373-4083


Mr. James P. O'Reilly, Regional Administrator  
U. S. Nuclear Regulatory Commission  
Region II  
101 Marietta Street, Suite 3100  
Atlanta, Georgia 30303

Re: McGuire Nuclear Station Unit 1  
Docket No. 50-369

Dear Mr. O'Reilly:

Reportable Occurrence Report RO-369/82-48 was to have been submitted by July 5, 1982. This 30 day reportable occurrence (per T.S.6.9.1.13) concerns T.S.3.4.5, "All power operated relief valves (PORVs) and their associated block valves shall be operable"; and T.S.3.3.3.6, "The accident monitoring instrumentation channels shown in Table 3.3-10 shall be operable", which were violated on June 5, 1982. At this time, investigation of the incident has not been completed. The report will be submitted by July 16, 1982.

Very truly yours,

  
William O. Parker, Jr.

PBN/jfw

cc: Document Control Desk  
U. S. Nuclear Regulatory Commission  
Washington, D. C. 20555

Records Center  
Institute of Nuclear Power Operations  
1820 Water Place  
Atlanta, Georgia 30339

Mr. P. R. Bemis  
Senior Resident Inspector-NRC  
McGuire Nuclear Station

OFFICIAL COPY

8207150129 820706  
PDR ADOCK 05000369  
S PDR

1822