

July 9, 1982

DJS LTR: #82/771

James G. Keppler, Regional Administrator Directorate of Regulatory Operations - Region III U. S. Nuclear Regulatory Commission 799 Roosevelt Road Glen Ellyn, Illinois 60137

Reportable Occurrence Report #82-27/01T-0 Docket #50-249 is being submitted to your office in accordance with Dresden Nuclear Power Station Technical Specification 6.6.B.l.(e), failure or malfunction of one or more components which prevents or could prevent, by itself, and the fulfillment of the functional requirements of system(s) used to cope with accidents analyzed in the SAR.

D.J. Scott

Station Superintendent

Dresden Nuclear Power Station

DJS:mb

Enclosure

cc: Director of Inspection & Enforcement

Director of Management Information & Program Control

U.S. NRC, Document Mgt. Branch

File/NRC