

50-373

July 7, 1982

James G. Keppler
Regional Administrator
Directorate of Regulatory Operations, Region III
U. S. Nuclear Regulatory Commission
799 Rooseve:t Road
Glen Ellyn, IL 60137

Dear Sir:

Reportable Occurrence Report #82-041/03L-0 Docket #050-373 is being submitted to your office in accordance with LaSalle County Nuclear Power Station Technical Specification 6.6.B.2.(c), observed inadequacies in the implementation of administrative or procedural controls which threaten to cause reduction of degree of redundancy provided in reactor protection systems or engineered safety feature systems.

R. H. Ho woak Superintendent

LaSalle County Station

RHH/GW/djp

Enclosure

cc: Director of Inspection & Enforcement
Director of Management Information & Program Control
U. S. NRC Document Management Branch
Inpo-Records Center
File/NRC

JUL 1 2 1982

TEXX