

FEB 10 1982

Dr. Joseph D. Lafleur, Jr.
Office of International Programs.
Mail Stop 8602

February 9, 1982

SUBJECT: Tube Degradation in Almaraz # 1 Steam Generators.

Dear Mr. Lafleur.

I am enclosing a copy of the documents mentioned bellow, that I have just received from the "Consejo de Seguridad Nuclear".

<u>Pages.</u>	<u>Title.</u>
1-58	Reparacion de los tubos de los Generadores de Vapor. C.N. de Almaraz-1. Rev. 0. Diciembre 1981. (Repair of SG tubes. Almaraz NPP Unit 1. Rev. 0. December 1, 1981). ---- In Spanish ----
59-77	✓ Almaraz-1 Tube Plugging. <u>W</u> Report. ---- In English ----
78	— Power History of Almaraz # 1 until November 3, 1981 ---- In Spanish ----
79-82	✓ Summary of actions taken by the CSN with Almaraz-1. ---- <u>In English</u> ----
83	— Power History form Dec. 20, 1981 ---- In Spanish ----
84	— Radiochemical Analysis of the secondary coolant from Dec. 20, 1981. ---- In Spanish ----
85 - 120	✓ C.N. de Almaraz. 500 Hours Report. <u>W</u> . Jan. 20, 1982 ---- <u>In English</u> ----

It is my understanding that all this information should be considered PROPRIETARY.

Due to the physical proximity of the Operating Reactors Assessment Branch I have already transmitted a copy of this information to Keith Wichman (ORAB/DL/NRR).

If somebody is interested in the information in Spanish I will be glad translating to English the required information.

Regards.

Jose I. Villadoniga.
SEP/DL/NRR. Mail Stop 516
Ph. 49-28933.