The information on this page is considered to be appropriate for public disclosure pursuant to 10 CFR 2.790.

U.S. NUCLEAR REGULATORY COMMISSION

Region V

Report No.	50-312/82-26 (IE-V-510)	
Docket No.	50-312 License No. DRP-54	Sa.eguards Group4
Licensee:	Sacramento Municipal Utility District	
	6201 S. Street, P. O. Box 15830	
	Sacramento, California 95813	
Facility Na	ame: Rancho Seco Nuclear Generating Station 1	
Inspection	at: 14440 Highway 104, Herald, California 95638	
Inspection	Conducted: July 9, 1982	
Date of La	st Material Control and Accounting Inspection Visit:	December 7, 1981
Type of In	spection: Announced Special Safeguards	
Inspectors: G. B. Nelson, Chemist		7-16-82 Date Signed
		Date Signed
		Date Signed
		Date Signed
Approved by	y L. R. Norderhaug, Chief, Safeguards Branch	7/14/82
	L. R. Norderhaug, Chief, Safeguards Branch	Date Signed
Inspection	Summary:	

Areas Inspected: Observation of an IAEA ad hoc inspection to audit the licensee's records and reports, install new film and batteries in two surveillance cameras.

The inspection involved 7 inspector-hours onsite.

Results: Within the scope of this inspection, no items of noncompliance were observed.