

SEP 2 1993

Docket Nos. 50-369, 50-370
License Nos. NPF-9, NPF-17

Duke Power Company
ATTN: Mr. T. C. McMeekin
Vice President
McGuire Site
12700 Hagers Ferry Road
Huntersville, NC 28078-8985

Gentlemen:

SUBJECT: NRC INSPECTION REPORT NOS. 50-369/93-12 AND 50-370/93-12

This refers to the inspection conducted by N. Economos and W. Kleinsorge of this office on July 19-23, and August 2-6, 1993. The inspection included a review of activities authorized for your McGuire facility. At the conclusion of the inspection, the findings were discussed with those members of your staff identified in the report.

Areas examined during the inspection are identified in the report. Within these areas, the inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observation of activities in progress.

The Ultrasonic examination of the reactor vessel identified a code rejectable indication, located on the outside wall of the vessel in weld W01 between the bottom head and the transition ring. On August 5, 1993 you discussed your findings with NRR and agreed to provide fracture analysis results and related information to the staff by August 16, 1993 for review.

Vendor supplied radiographs for replacement heat exchanger (2NS), nozzles A and B were in part code rejectable. Failure to meet construction code requirements and the inability to reradiograph the subject welds requires that you submit a request for code relief for the partial examination of the subject nozzle welds.

Within the scope of the inspection, violations or deviations were not identified.

In accordance with 10 CFR 2.790 of the NRC's "Rules of Practice," a copy of this letter and its enclosure will be placed in the NRC Public Document Room.

130057

9305130152 930902
PDR ADDCK 05000369
G PDR

11
IE01

Should you have any questions concerning this letter, please contact us.

Sincerely,

Original signed by
M. B. Shymlock/for
Caudle A. Julian, Chief
Engineering Branch
Division of Reactor Safety

Enclosure:
NRC Inspection Report

cc w/encl:
R. O. Sharpe
Compliance
Duke Power Company
12700 Hagers Ferry Road
Huntersville, NC 28078-8985

G. A. Coop
Licensing - EC050
Duke Power Company
P. O. Box 1006
Charlotte, NC 28201-1006

A. V. Carr, Esq.
Duke Power Company
422 South Church Street
Charlotte, NC 28242-0001

J. Michael McGarry, III, Esq.
Winston and Strawn
1400 L Street, NW
Washington, D. C. 20005

Dayne H. Brown, Director
Division of Radiation Protection
N. C. Department of Environment,
Health & Natural Resources
P. O. Box 27687
Raleigh, NC 27611-7687

County Manager of Mecklenburg County
720 East Fourth Street
Charlotte, NC 28202
(cc w/encl cont'd - See page 3)

SEP -2 1993

(cc w/encl cont'd)
T. Richard Puryear
Nuclear Technical Services Manager
Carolinas District
Westinghouse Electric Corporation
P. O. Box 32817
Charlotte, NC 28232

Dr. John M. Barry, Director
Mecklenburg County Department
of Environmental Protection
700 North Tryon Street
Charlotte, NC 28203

Karen E. Long
Assistant Attorney General
N. C. Department of Justice
P. O. Box 629
Raleigh, NC 27602

bcc w/encl:
V. Nerses, NRR
R. Watkins, RII
M. S. Lesser
J. P. Jaudon, RII
G. A. Hallstrom, RII
A. R. Herdt, RII
Document Control Desk

NRC Resident Inspector
U.S. Nuclear Regulatory Commission
12700 Hagers Ferry Road
Huntersville, NC 28078-8985

File Name: S:\DRS\EB\MCG93-12.NE

RII:DRS

WPKleinsorge
08/16/93

RII:DRS

NEconomos
08/16/93

RII:DRS

J. Blake
08/16/93

RII:DRP

MLesser
08/16/93