

Yellow

JUL 28 1982

Westinghouse Electric Corporation
ATTN: Mr. M. D'Amore, Manager
Columbia Plant
Nuclear Fuel Division
Drawer R
Columbia, SC 29250

Gentlemen:

Subject: Report No. 70-1151/82-13

This refers to the routine safeguards inspection conducted by Mr. J. W. Sabados of this office on July 6-9, 1982, of activities authorized by NRC License No. SMN-1107 at Westinghouse - Columbia facility and to the discussions of our findings held with you and members of your facility at the conclusion of the inspection.

Areas examined during this inspection included your program for nuclear material control and accountability under the applicable provisions of Title 10, Code of Federal Regulations, Part 70, "Special Nuclear Material," and specific license conditions. Within these areas, the inspection consisted of selective examinations of procedures and representative records, interviews with personnel, performance tests, and observations by the inspector.

Within the scope of this inspection, no violations or deviations were disclosed.

We have examined actions you have taken with regard to a previously reported unresolved matter. The status of this item is discussed in the enclosed report.

One new unresolved item resulted from this inspection and is discussed in the enclosed report. This item will be examined during subsequent inspections.

In accordance with Section 2.790(d) of the NRC's "Rules of Practice", Part 2, Title 10, Code of Federal Regulations, activities involving safeguards and security measures are exempt from public disclosure; therefore, the enclosed report with the exception of the cover page, which is an inspection summary, will not be placed in the Public Document Room.

8208030629 820728
PDR ADOCK 07001151
C PDR

MATERIAL TRANSMITTED HEREWITH
CONTAINS 2.790 INFORMATION

IE03

Westinghouse Electric Corporation

2

JUL 28 1982

Should you have any questions concerning this letter, we will be glad to discuss them with you.

Sincerely,

/s/

A. F. Gibson, Chief
Technical Inspection Branch
Division of Engineering and
Technical Programs

Enclosures:

1. Inspection Report No. 70-1151/82-13
(Exempt from Disclosure)
2. Inspection Summary
(Not Exempt)

bcc w/o encl:
License Fee Management Branch

bcc w/Inspection Summary:
State of South Carolina

bcc w/encl:
Document Management Branch
Chief of Safeguards Branch, DSRSI
Chief, MC&A, Licensing Branch, NMSS

RII

JWSabado:ht
7/28/82

RII

GE Tyne
7/28/82

RII

EJMcAuliffe
7/28/82

RII

AFGibson
7/28/82