



July 27, 1982

DIRECTOR OF NUCLEAR REACTOR REGULATION ATTENTION JOHN F STOLZ CHIEF OPERATING REACTORS BRANCH 4 U S NUCLEAR REGULATORY COMMISSION WASHINGTON DC 20555

DOCKET 50-312
RANCHO SECO NUCLEAR GENERATING STATION
UNIT NO 1
MANUAL BYPASS OF AUXILIARY FEEDWATER AUTO INITIATION

In a telephone conversation on July 16, 1982, Mr. Mark Padovan of the NRC asked if manual bypass of the auxiliary feedwater auto initiation would be annunciated in the control room at Rancho Seco Unit 1. The new control system will annunciate in the control room when the auxiliary feedwater auto initiator is bypassed.

If we can provide any additional information, please advise.

John J. Mattimoe

Assistant General Manager

and Chief Engineer

A001

8208040001 820727 PDR ADDCK 05000312 PDR