

October 5, 1990

P137

Mr. Wade Green
Institute of Nuclear Power Operations
Suite 1500, 1100 Circle 75 Parkway
Atlanta, Georgia 30339-3064

Dear Mr. Green:

Enclosed for your information is our biweekly listing of generic communications being considered or under development by the NRC staff. These include Bulletins (type coded BL on the list), Information Notices (IN) and Generic Letters (GL). Temporary Instructions, that cover the special NRC inspection effort resulting from certain generic communications, are listed with the type code TI. This listing includes all proposed generic communications that had been reported to us by October 3, 1990. The dates given are the ending dates for the quarter during which we expect the listings to be issued.

Sincerely,

Original Signed By
Carl H. Berlinger
Carl H. Berlinger, Chief
Generic Communications Branch
Division of Operational Events Assessment
Office of Nuclear Reactor Regulation

Enclosure:
As stated

DISTRIBUTION w/enclosure:

- All NRC Division Directors
- All NRC Branch Chiefs
- WTRussell, NRR
- CERossi, NRR
- CHBerlinger, NRR
- OGCB Members
- TMendiola, NRR
- RFraleley, ACRS
- JLieberman, OE
- PDR

Central Files

- DCB
- DOEA R/F
- OGCB R/F
- DKirkpatrick R/F
- SRichardson, DOE
- RBarber, DOE
- ENowstrup, DOE

9010240331 901005
PDR ORG EPSINFO
PDC

Document Name: LETTER TO GREEN
OGCB:DOEA:NRR C/OGCB:DOEA:NRR
DCKirkpatrick CHBerlinger
10/4/90 DCK 10/4/90

NRC FILE CENTER COPY

DF01

RD-25
INPO

11

October 5, 1990

Page No. 1
10/03/90PROPOSED GENERIC COMMUNICATIONS
IN PREPARATION WITHIN THE NRC

TP ORIGINATING OFFICE	SUBJECT	CONTACT	PHONE	EST DATE QTR END
IN NRR/DRIS RVIB	ENVIRONMENTAL QUALIFICATION OF LIMITORQUE MOV ACTUATOR TERMINAL BLOCKS & MARATHON 1600 TERMINAL BLOCKS	Steve Alexander	(301) 492-0995	12/31/90
GL NRR/DEST ESGB	NRR RECOMMENDATION ON ISI OF MARK I & II STEEL CONTAINMENTS, REFUELING CAVITIES & ASSOCIATED DRAINAGE SYSTEMS	Chen P. Tan	(301) 492-3315	06/30/91
GL NRR/DEST SELB	RESOLUTION OF GI B-56, DIESEL RELIABILITY	Om P. Chopra	(301) 492-0781	12/31/90
TI NRR/DEST EMEB	INSPECTION OF IMPLEMENTATION OF GENERIC LETTER 89-10: "SAFETY RELATED MOTOR OPERATED VALVE TESTING AND SURVEILLANCE"	Tom Scarbrough	(301) 492-0794	06/30/91
GL NRR/DEST SPLB	CONTROL ROOM HABITABILITY SYSTEMS	Charles Nichols	(301) 492-0856	12/31/90
IN NRR/DOEA OGCB	DIESEL GENERATOR FUEL OIL OXIDATION	Vernon Hodge	(301) 492-1861	12/31/90
BL NRR/DEST ECEB	EVALUATION OF HAZARDS ASSOCIATED WITH HYDROGEN, NITROGEN AND PROPANE USED IN NUCLEAR POWER PLANTS	Frank J. Witt	(301) 492-0767	12/31/90
TI NRR/DEST EMEB	INSPECTION OF IMPLEMENTATION OF GL 89-04: "GUIDANCE ON DEVELOPING ACCEPTABLE INSERVICE TESTING PROGRAMS"	Ted Sullivan	(301) 492-3270	12/31/90
TI NRR/DRIS RSIB	ELECTRICAL DISTRIBUTION FUNCTIONAL INSPECTION	E. V. Imbro	(301) 492-0954	12/31/90
GL RES/DSIR EIB	POTENTIAL CONCERNS REGARDING PWR REACTOR VESSEL DESIGN ADEQUACY UNDER NATURAL CONVECTION COOLDOWN TRANSIENT CONDITIONS	Joel Page	(301) 492-3941	12/31/90
BL NRR/DRIS RVIB	NONCONFORMING MATERIALS SUPPLIED BY MEREDITH CORPORATION, (PRESSURE VESSEL NUCLEAR) OF HILLSIDE NEW JERSEY	R. Cilimberg	(301) 492-0945	12/31/90
GL RES/DSIR EIB	RESOLUTION OF GI-29, BOLTING DEGRADATION OR FAILURE IN NUCLEAR POWER PLANTS	T. Y. Chang	(301) 492-3922	03/31/91

10/03/90

PROPOSED GENERIC COMMUNICATIONS
IN PREPARATION WITHIN THE NRC

TP ORIGINATING OFFICE	SUBJECT	CONTACT	PHONE	EST DATE QTR END
GL RES/DSIR EIB	RESOLUTION OF GI A-30, ADEQUACY OF SAFETY-RELATED DC POWER SUPPLIES	Dale Thatcher	(301) 492-3935	12/31/90
GL RES/DSIR EIB	RESOLUTION OF GI 48, LCOS FOR CLASS 2 VITAL INSTRUMENT BUS AND G... INTERLOCKS AND LCO FOR CLASS 2 TIE BREAKERS	Dale Thatcher	(301) 492-3935	12/31/90
GL NRR/DOEA OTSB	LINE ITEM TECH SPEC IMPROVEMENT: CHANGING TECHNICAL SPECIFICATION SURVEILLANCE INTERVALS FROM 18 TO 24 MONTHS	Tom Dunning	(301) 492-1189	03/31/91
GL NRR/DOEA OTSB	LINE-ITEM TECH SPEC IMPROVEMENT - DIESEL GENERATOR TESTING	Ed Tomlinson	(301) 492-3150	12/31/90
IN NRR/DRIS VIB	INADEQUATE VENDOR ESTABLISHMENT AND IMPLEMENTATION OF 10CFR PART 21 PROCEDURES	Joe Petrosino	(301) 492-0979	03/31/91
IN NRR/DRIS VIB	COUNTERFEITING OF CRANE VALVES	Steven M. Matthews	(301) 492-3191	12/31/90
BL NRR/DRIS RVIB	MALFUNCTION OF BORG-WARNER BOLTED BONNET CHECK VALVES CAUSED BY FAILURE OF THE SWING ARM	Robert Pettis Jr.	(301) 492-3214	12/31/90
IN NRR/DEST SPLB	PREVIOUSLY UNIDENTIFIED UNFILTERED RELEASE PATH	Charles R. Nichols	(301) 492-0854	12/31/90
IN NRR/DOEA OEAB	INADEQUATE SEPARATION OF NON-CLASS-1E UV/UF CIRCUITRY FROM REACTOR PROTECTION CIRCUITRY AT TROJAN	Walton Jensen	(301) 492-1157	12/31/90
IN NRR/DOEA OEAB	STRESS CORROSION CRACKING OF REACTOR COOLANT PUMP BOLTS	Walton Jensen	(301) 492-1157	12/31/90
BL NRR/DET EMCB	STEAM GENERATOR TUBE EXPANSION TRANSITION CRACKING	Emmett Murphy	(301) 492-0710	12/31/90
IN NRR/DEST SELB	ADEQUACY OF EMERGENCY AND ESSENTIAL LIGHTING	N. K. Trehan	(301) 492-0807	12/31/90
IN NRR/DST SICB	INSTALLATION OF DIGITAL MICROPROCESSORS INTO SAFETY SYSTEMS VIA 10 CFR 50.59	James Stewart	(301) 492-0824	12/31/90

10/03/90

PROPOSED GENERIC COMMUNICATIONS
IN PREPARATION WITHIN THE NRC

TP ORIGINATING OFFICE	SUBJECT	CONTACT	PHONE	EST DATE QTR END
IN NRR/DST SICB	MISAPPLICATION OF TEMPERATURE CONTROLLER LEADS TO TECHNICAL SPECIFICATION ACTION AT NUCLEAR POWER PLANT	Vincent Thomas	(301) 492-0845	12/31/90
IN AEOD	OPERATIONAL EXPERIENCE ON BUS TRANSFER	Subinoy Mazumdar	(301) 492-2408	12/31/90
GL NRR/DEST SELB	GROUNDS IN DIRECT CURRENT DISTRIBUTION SYSTEMS	F. Burrows	(301) 492-3260	12/31/90
IN NRR\DRIS RSGB	BACKGROUND INVESTIGATION FOR GRANTING UNESCORTED ACCESS	Nancy Ervin	(301) 492-0946	12/31/90
GL NRR\DRIS RSGB	REPORTING OF SAFEGUARDS EVENTS	Nancy Ervin	(301) 492-0946	12/31/90
IN NRR/DOEA OGCB	IMPROPER SETTING OF RELIEF VALVES DUE TO TESTING AT CONDITIONS DIFFEREDNT FROM THOSE EXPERIENCED IN NORMAL OPERATIONS	Andy Kugler	(301) 492-0834	12/31/90
IN REGION II	POTENTIAL PROBLEMS WITH HEATING VENTILATION AND AIR CONDITIONING SYSTEMS	M. P. Shymlock	(404) 331-4196	12/31/90
IN REGION II	SEIMENS-ITE MOLDED CASE CIRCUIT BREAKER FAILURES	Steve Alexander		12/31/90
BL NRR/DET EMCB	[NEW] SUPPLRMENT TO NRC BULLETIN 89-01: FAILURE OF WESTINGHOUSE STEAM GENERATOR TUBE MECHANICAL PLUGS	Emmett Murphy	(301) 492-0710	12/31/90
IN NRR/DEST	[NEW] CORROSION OF VALVE-TO-TORQUE TUBE KEYS IN SPRAY POND CROSS CONNECT VALVES	David Terao	(301) 492-3317	12/31/90
IN NRR/DOEA OEAB	[NEW] IN 88-23, SUPP. 3: POTENTIAL FOR GAS BINDING OF HIGH-PRESSURE SAFETY INJECTION PUMPS DURING A LOSS OF COOLANT ACCIDENT	John Thompson	(301) 492-1171	12/31/90