DCD/DCB

OCT 2 6 1990

License No. 34-18882-01

H. C. Nutting Company ATTN: J. L. Lindsey Vice President 4120 Airport Road Cincinnati, OH 45226

Gentlemen:

Enclosupper

This refers to the special safety inspection conducted by K. J. Lambert of this office on September 18, 1990, of activities authorized by NRC Byproduct Material License No. 34-18882-01 and to the discussion of our findings with you at the conclusion of the inspection.

The enclosed copy of our inspection report identifies areas examined during the inspection. Within these areas, the inspection consisted of a selective examination of procedures and representative records, etcervations, and interviews with personnel.

During this inspection, certain of your activities appeared to be in violation of NRC requirements, as specified in the enclosed Notice. A written response is required.

In accordance with 10 CFR 2.790 of the Commission's regulations, a copy of this letter, the enclosures, and your response to this letter will be placed in the NRC Public Document Room.

The responses directed by this letter and the accompanying Notice are not subject to the clearance procedures of the Office of Management and Budget as required by the Paperwork Reduction Act of 1980, PL 96-511.

We will gladly discuss any questions you have concerning this inspection.

Sincerely,

William H. Schultz, Chief Nuclear Materials Safety Section 1

1. Notice of V 2. Inspection No. 030-1	iolation Report 7304/90001(DRSS)		
cc w/enclosures DCD/DCB (RIDS)	:		
RIIIKes	RIII	BAY	
Lambert/sd	Schultz	herold	
10/22/20	10-26-90 9011130177 90 REG3 L1C30 34-18882-01	01026	
	REG3 L1030 34-19882-01	PDC	