

Appendix

NOTICE OF VIOLATION

Cleveland Crystals, Inc.

License No. 34-20075-01

As a result of the inspection conducted on July 30, 1982, and in accordance with the NRC Enforcement Policy, 47 FR 9987 (March 9, 1982), the following violation was identified:


Condition No. 14 of your license requires that you test your sealed sources containing licensed material for leakage and/or contamination at intervals not to exceed six months.

Contrary to this requirement, as of the day of the inspection, your 10 millicurie americium-241 sealed source was last leak tested for contamination or leakage on July 14, 1981. An interval of more than six months.

This is a Severity Level IV violation (Supplement VI).

Pursuant to the provisions of 10 CFR 2.201, you are required to submit to this office within thirty days of the date of this Notice a written statement or explanation in reply, including for each item of noncompliance: (1) corrective action taken and the results achieved; (2) corrective action to be taken to avoid further noncompliance; and (3) the date when full compliance will be achieved. Consideration may be given to extending your response time for good cause shown.

8-5-82  
Dated

  
\_\_\_\_\_  
D. J. Sreniawski, Chief  
Materials Radiation Protection  
Section 2