



CONNECTICUT YANKEE ATOMIC POWER COMPANY

BERLIN, CONNECTICUT

P. O. BOX 270 HARTFORD, CONNECTICUT 06101

TELEPHONE
203-666-6911

December 13, 1978
GTS-78-E-540

Mr. Boyce Grier, Director
Region 1
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
631 Park Avenue
King of Prussia, Pennsylvania 19406

Reference: Facility Operating License No. DPR-61
Docket No. 50-213
ETS/NR/50-213/78-13

Dear Mr. Grier:

Pursuant to Connecticut Yankee Environmental Technical Specifications (ETS) Section 3.1.1.3, Connecticut Yankee Atomic Power Company hereby forwards the following report regarding the loss of a twenty-four hour sample. On this day, November 12, 1978, divers were contracted to clean the intake structure trash racks. This debris was removed and placed into the fish impingement basket. The contents in the basket were discarded at the completion of cleaning, resulting in the accidental loss of the twenty-four hour sample.

Very truly yours,

Richard H. Graves
Station Superintendent

HRP/ngt

cc: Director, Office of Nuclear Reactor Regulation, Washington, D.C. (17)

7812220061

C003/ES
110