


July 7, 1982

DJS Ltr. #82-763

James G. Keppler, Regional Administrator
Directorate of Regulatory Operations - Region III
U.S. Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, IL 60137

Updated report on Reportable Occurrence Report #82-14/03X-1, Docket #050-237 is being submitted to your office in accordance with Dresden Nuclear Power Station Technical Specification 6.6.B.2.(d), abnormal degradation of systems other than those specified in item B.1.e. above designed to contain radioactive material resulting from the fission process. Incorrectly referenced Docket number stated in original Reportable Occurrence as 050- 249.



D. J. Scott
Station Superintendent
Dresden Nuclear Power Station

DJS/nh

Enclosure

cc/ Director of Inspection & Enforcement
Director of Management Information & Program Control
U.S. NRC, Document Management Branch
File/NRC