FORM NRC-591 (3-77)

U.S. NUCLEAR REGULATORY COMMISSION

OFFICE OF INSPECTION AND ENFORCEMENT

30-13747

INSPECTION FINDINGS AND LICENSEE ACKNOWLEDGMENT

1. LICENSEE			2. REGIONAL OFFICE		
Department of the Navy USS DIXON (AD 37) FPO San Diego, CA 92133			U.S. NUCLEAR REGULATORY COMMISSION 1450 MARIA LANE, SUITE 210 WALNUT CREEK, CA 94596		
3. DOCK	ET NUMBER(S)	4. LICENSE NUMBER(S)		B. DATE OF INSPECTION	
		04-17976	-01	17 Jule 82	
The inspe		iditions of your license. The i	aspection consisted of sel	radiation safety and to compliance with the lective examinations of procedures and repre- of this inspection are as follows:	
No items of noncompliance or unsafe conditions were found.					
The fol	llowing items of noncompliance re	lated to records, signs, an	d labels were found:		
A. Rooms or areas were not properly posted to indicate the presence of a RADIATION AREA. 10 CFR 20.203(b) or 34.42					
□ B	B. Rooms or areas were not properly posted to indicate the presence of a HIGH RADIATION AREA. 10 CFR 20.203(c) (1) or 34.42				
	C. Rooms or areas were not properly posted to indicate the presence of an AIRBORNE RADIOACTIVITY AREA. 10 CFR 20.203(d)				
	D. Rooms or areas were not properly posted to indicate the presence of RADIOACTIVE MATERIAL. 10 CFR 20.203(e)				
	E. Containers were not properly labeled to indicate the presence of RADIOACTIVE MATERIAL. 10 CFR 20.203(f) (1) or (f) (2)				
□ F	F. A current copy of 10 CFR 20, a copy of the license, or a copy of the operating procedures was not properly posted or made available. 10 CFR 20.206(b)				
	G. FormNRC-3 was not properly posted. 10 CFR 20.206(c)				
□ H	H. Records of the radiation exposure of individuals were not properly maintained. 10 CFR 20.401(a) or 34,33(b)				
	I. Records of surveys or disposals were not properly maintained. 10 CFR 20.401(b) or 34.43(d)				
	J. Records of receipt, transfer, disposal, export or inventory of licensed material were not properly maintained. 10 CFR 30.51, 40.61 or 70.51				
	K. Records of leak tests were not maintained as prescribed in your license, or 10 CFR 34.25(c)				
	L. Records of inventories were not maintained. 10 CFR 34.26				
	M. Utilization logs were not maintained. 10 CFR 34.27				
	N. Records of radiation survey instrument calibration were not maintained. 10 CFR 34.24				
	O. Records of teletherapy electrical interlock tests were not maintained as prescribed in your license.				
	P. Other				
		Paul	R Zurak	ouzhi ctor)	
7. The NRC Inspector has explained and I understand the items of poncompliance listed above. The items of noncompliance will be corrected within the next 30 days.					
8208130084 820617 NMS LIC20 04-17976-01 PDR					
(Date)			(Licensee Representative - Title or Position)		