IRC Form 591 12-81) 0 CFR 2-201	SAFETY	NSPECTION	U.S. NUCLEAR REGULA	TORY COMMISSION
Werner G. Schroffner, M.D. The Fronk Clinic 839 South Beretania Street Honolulu, HI 96814		2 REGIONAL OFFICE U.S. NUCLEAR REGULATORY COMMISSION 1450 MARIA LANE, SUITE 210 WALNUT CREEK, CA 94596		
DOCKET NUMBER(S)	4. LICENSE NUMBERIS		5. DATE OF INSPECTION June 28, 1982	
censee: he inspection was an examination of the activitie egulatory Commissions (NRC) rules and regulati id representative records, interviews, with persor 1. Within the scope of this inspection, no viola 2. The inspector also verified the steps you ha	ons and the conditions of yo nnel, and observations by the ations were observed.	ur license. The inspec inspector. The findin	tion consisted of selective examin gs as a result of this inspection at	nations of procedures re as follows:
Of a	:h is required to be posted in	accordance with 10 C	FR 19.11 was not properly posted to	o indicate the presenc , (c), (d), (e) or 34,42 were not properi
C frequencies. 10 CFR			of sealed sources were not per Condition Number	erformed at the prope
D. Records of 10 CFR		or License Condition		t properly maintained
	r otherwise made available. T		the second s	ot made in accordanc
H				
J				
hereby state that within 30 days the actions desc	ribed by me to the Inspector	will be taken to corre	ct the violations identified in the	items checked above
B208130168 B20628	ordance with the requirement	hts of 10 CFR 2.201. P		ttea ameri radaned p