## Community Memorial GENERAL HOSPITAL



LA GRANGE, ILLINOIS 60525 PHONE 352-1200

July 12, 1982

Mr. J. R. Miller, Chief Technical Inspection Branch United States Nuclear Regulatory Commission Region III 799 Roosevelt Road Glen Ellyn, Illinois 60137

Re: License No. 12-03306-05 30-9420

Dear Mr. Miller:

During his routine safety inspection of June 2, 1982, Mr. J. R. Madera found five items of noncompliance in our Nuclear Medicine Department. I have listed below each item and the corrective action taken to bring us into compliance.

1. Food in the "hot lab" refrigerator.

We have instructed all personnel in the Medical Imaging area that food and drink are not allowed in the Nuclear Medicine Department. In addition, the refrigerator in the "hot lab" is now posted with a sign stating that no food or drink is to be placed within.

2. Xenon trapping device not checked for leakage or saturation.

The Xenon trap is now being checked on a regular basis as recommended. Documentation of this is found in the Radiation Monitoring log as well as the Quality Assurance book in the department.

3. Wearing of disposable gloves while handling radioactive materials.

All personnel have been reinstructed in the necessity of wearing gloves while handling radioactivity. Boxes of gloves are now placed in prominent locations throughout the department for ready access.

4. Calibration of Dose Calibrator.

During his visit Mr. Madera instructed our personnel in the accepted method of doing quarterly linearity checks. We have revised our procedure IE HQ FILE COPY to follow this accepted method.

DMB: IEO7

JUI 14 1982

8208130250 820712 NMS LIC30 12-03306-05 PDR Sincerely,

Joseph P. Calandra Administrator

JPC:bjc