PDR.

DAIRYLAND POWER COOPERATIVE

La Crosse, Wisconsin

54601

January 30, 1979

In reply, please refer to LAC-6095

DOCKET NO. 50-409

Mr. James G. Keppler Regional Director U. S. Nuclear Regulatory Commission Directorate of Regulatory Operations Region III 799 Roosevelt Road Glen Ellyn, Illinois 60137

SUBJECT: DAIRYLAND POWER COOPERATIVE LA CROSSE BOILING WATER REACTOR (LACEWR) PROVISIONAL OPERATING LICENSE NO. DPR-45 IE BULLETIN NO. 78-12A - ATYPICAL WELD MATERIAL IN REACTOR PRESSURE VESSEL WELDS

- Reference: (1) NRC Letter, Keppler to Linder, dated November 24, 1978.
 - (2) DPC Letter, LAC-6012, Linder to Keppler, dated November 27, 1978.
 - (3) NRC Letter, Keppler to Madgett, dated September 29, 1978.

Dear Mr. Keppler:

In response to your letter (Reference 1) which contained IE Bulletin No. 78-12A, in which the response requirements for IE Bulletin No. 78-12 have been modified, please refer to our letter (Reference 2) which contains all available information requested by IE Bulletin No. 78-12 (Reference 3).

If there are any questions concerning this response, please contact us.

Very truly yours,

DAIRYLAND POWER COOPERATIVE

front finde

Frank Linder, General Manager

FL:HAT:af

9 1979

7903150419