Dbcket No. 50-602

November: 26, 1990

Dr. Thomas L. Bauer Assistant Director Nuclear Engineering Teaching Laboratory The University of Austin at Texas 10100 Burnet Road Austin, Texas 78758

Dear Dr. Bauer:

SUBJECT: MATERIAL REQUIRED TO COMPLETE EVALUATION FOR ISSUANCE OF OPERATING LICENSE

A review of our records shows that the following information is required to complete our evaluation for issuance of an operating license for the University of Texas at Austin TRIGA Research Reactor.

1. Updated Emergency Plan

2. Updated Operator Requalification Plan

3. Final Technical Specifications and Bases

In addition, three items were identified as remaining open by our inspection program.

- 1. Open item 602/8904-05, repair and calibration of the Argon-41 monitor.
- Open item 602/8904-06, installation/testing of the HVAC system HEPA filter.
- Open item 602/9003-01, receipt and installation of a new beam port shield plug.

If these items are not closed before issuance of an operating license, closure of these items before fuel loading will be a condition of the operating license.

If you have any questions concerning the issuance of your facility operating license, please contact Alexander Adams, Jr., at (301) 492-1127.

Sincerely,

original signed by

Seymour H. Weiss, Director Non-Power Reactors, Decommissioning and Environmental Projects Directorate Division of Reactor Projects and Special Projects Office of Nuclear Reactor Regulation

cc: See next page

DISTRIBUTION Docket file 50-602 NRC & Local PDRs NRDE r/f DCrutchfield WTravers EHylton

AAdams OGC EJordan ACRS (10) Plant file Region IV

[AA LTR2 TBAUER]

NADE:LA ENviton 11/26/90

NRDE: PM AAdams dmj 11/26/90

SWeiss 11/2/0/90



UNITED STATES NUCLEAR REGULATORY COMMISSION WASHINGTON, D. C. 20555

November 26, 1990

Docket No. 50-602

> Dr. Thomas L. Bauer Assistant Director Nuclear Engineering Teaching Laboratory The University of Austin at Texas 10100 Burnet Road Austin, Texas 78758

Dear Dr. Bauer:

SUBJECT: MATERIAL REQUIRED TO COMPLETE EVALUATION FOR ISSUANCE OF OPERATING LICENSE

A review of our records shows that the following information is required to complete our evaluation for issuance of an operating license for the University of Texas at Austin TRIGA Research Reactor.

1. Updated Emergency Plan

Updated Operator Requalification Plan 2.

3. Final Technical Specifications and Bases

In addition, three items were identified as remaining open by our inspection program.

1. Open item 602/8904-05, repair and calibration of the Argon-41 monitor.

 Open item 602/8904-06, installation/testing of the HVAC system HEPA filter.
Open item 602/9003-01, receipt and installation of a new beam port shield plug.

If these items are not closed before issuance of an operating license, closure of these items before fuel loading will be a condition of the operating license.

If you have any questions concerning the issuance of your facility operating license, please contact Alexander Adams, Jr., at (301) 492-1127.

Sincerely.

Sequers H. Weiss

Seymour H. Weiss, Director Non-Power Reactors, Decommissioning and Environmental Projects Directorate Division of Reactor Projects and Special Projects Office of Nuclear Reactor Regulation

cc: See next page

University of Texas

:03

.

. . . .

11 4

Governor's Budget and Planning Office P. O. Box 13561 Austin, Texas 78711

Mr. Thomas Bauer Nuclear Reactor Laboratory University of Texas Austin, Texas 78712

Bureau of Radiation Control State of Texas 1100 West 49th Street Austin, Texas 78756

Mr. R. Jacobi 7300 Grass Cove Austin, Texas 78759

Mr. Auburn Mitchell Office of the Governor P. O. Box 12428 Austin, Texas 78711