

AUG 11 1982

Perry Memorial Hospital
ATTN: Mr. Harold L. Autrey
Hospital Administrator
530 Park Avenue East
Princeton, Illinois 61356

License No. 12-15671-01

Gentlemen:

This refers to the routine safety inspection conducted by Dr. L. W. Shatterly of this office on July 30, 1982, of activities authorized by NRC Byproduct Material License No. 12-15671-01 and to the discussion of our findings with Mr. William Spittler and selected members of your staff at the conclusion of the inspection.


The inspection was an examination of activities conducted under your license as they relate to radiation safety and to compliance with the Commission's rules and regulations and with the conditions of your license. The inspection consisted of a selective examination of procedures and representative records, observations, independent measurements, and interviews with personnel.

In addition to the above areas, the inspector examined actions described in your letter dated January 2, 1980, regarding apparent items of noncompliance found during our November 28, 1979, inspection. We have no further questions regarding these matters.

No items of noncompliance with NRC requirements were identified during the course of this inspection.

We will gladly discuss any questions you have concerning this inspection.

Sincerely,



D. G. Wiedeman, Chief
Materials Radiation Protection
Section 1

cc: Paul A. Pelaez - Antelo, M.D. (RPO)
DMB/Document Control Desk (RIDS)

RIII <i>LWS</i> Shatterly/sv 8/6/82	RIII <i>D.G.</i> Wiedeman 8/9/82	RIII <i>D.G.</i> Miller for
--	---	--------------------------------------

IE HQ FILE COPY

8208160103 820811
NMS LIC30
12-15671-01 PDR

DMB IE-07