

PART 21 IDENTIFICATION NO. 80-251-003 COMPANY NAME Bergex-Palmer ^{Palmer}

DATE OF LETTER 8/14/80 DOCKET NO. _____

DATE DISTRIBUTED 8/22/80 ORIGINAL REPORT SUPPLEMENTARY

DISTRIBUTION:

REACTOR (R)

FUEL CYCLE &

SAFEGUARDS (S)

IE FILES

MATERIALS (M)

IE FILES

AD/ROI (2)

IE FILES

AD/SG

AD/RCI

AD/FFMSI

AD/ROI

REGIONS I,II,III,IV,V

REGIONS I,II,III,IV,V

REGIONS I,II,III,IV,V

VENDOR BR. R-IV

VENDOR BR. R-IV

VENDOR BR. R-IV

LOEB / MPA MNB 5715

NMSS / FCMS SS-396

NRR/DOL

AEOD MNB 7602

LOEB / MPA MNB 5715

NMSS / SG SS-881

NRR/DOE

AEOD MNB 7602

LOEB / MPA MNB 5715

NRR/DSI

ASLBP E/W 450

AEOD MNB 7602

NRR/DST

SAP/SP MNB-7210A

ASLBP E/W 450

NRR/DOL

CENTRAL FILES 016

CENTRAL FILES 016

ASLBP E/W 450

CENTRAL FILES (CHRON)

CENTRAL FILES (CHRON)

CENTRAL FILES 016

PDR

CENTRAL FILES SS-396

CENTRAL FILES (CHRON)

LPDR

PDR

PDR

TERA

LPDR

LPDR

TERA

TERA

ACTION:

PRELIMINARY EVALUATION OF THE ATTACHED REPORT INDICATES LEAD RESPONSIBILITY FOR FOLLOWUP AS SHOWN BELOW:

IE

NRR

NMSS

OTHER

PT 21

RCI
ROI
SG
FFMSI

8009120699

REV. 8/1/80



BERGEN-PATERSON
PIPESUPPORT CORPORATION

Mr. Bruce Gruber
48 WINNISQUAM AVENUE
LAGONIA, NEW HAMPSHIRE 03246

August 14, 1980

80-251-003

Bechtel Power Corporation
15740 Shady Grove Road
Gaithersburg, MD 20760

Attention: Project Engineer
SNURPS Project

Subject: SNURPS Project
Bechtel Job 10466
P.O. # 10466-M218A, M220
B/P Jobs 7500/7502 and
7520/7522
Report of Deficiencies
CCN: 7500/32/0669
Reference: B/P Letter: CCN: 7500/32/0669
Same subject, dated 7/14/80

Dear Sir:

In regard to reference, we are submitting the following revised list of items affected. This revised list contains only the hangers actually shipped to the jobsite. Listing in referenced CCN contained all items presently in process and items already shipped to the jobsite. In process items shall be corrected before shipment is made, thus eliminating any field action on them.

| <u>Hanger Mark No.</u> | <u>Qty.</u> | <u>Size</u> | <u>B/P Job</u> |
|------------------------|-------------|-------------|-------------------|
| EM01-R/30/112 (C) | 1 | 2541-.65 | 7502 - Wolf Creek |
| EM01-0045/112 (C) | 1 | 2541-.65 | 7502 - Wolf Creek |

In recent conversation with your Mr. Bruce Gruber it was noted that a Hanger Mark Number for B/P Job 7502 - Wolf Creek, was typed incorrectly on reference listing. Hanger Mark Number EM11-R501/841 should read as EM11-R501/041.

If we can be of any further assistance please do not hesitate to call.

Sincerely,

BERGEN-PATERSON PIPESUPPORT CORP.

W.P. Beckstead

W.P. Beckstead
Manager of Quality Assurance

W.P. Beckstead

cc See page 4

August 14, 1980

TO: Bechtel Power Corporation
FROM: W.F. Becksted
SUBJECT: SNUPPS Project
Report of Deficiencies
ATT: Project Engineer
SNUPPS Project

cc: R. Baird
H. Erikson
H. Noreen
D. Paterson
S. Paterson
P. Cagne
J. Stinson
C. Strout
G. Palmer
Q.A. File (1)
Mr. Boyce H. Crier, U.S. NRC
Mr. Frank B. Field
Q.A. Manager
Union Electric Company
P.O. Box 140
St. Louis, Missouri 63166
Mr. Earl W. Creel
Q.A. Manager
Kansas Gas & Electric Co.
P.O. Box 208
Wichita, Kansas 67201