

JUL 15 1982

APPENDIX A
NOTICE OF VIOLATION

Meloy Laboratories, Inc.

License No. 45-13733-01

As a result of the inspection conducted on July 1, 1982, and in accordance with the NRC Enforcement Policy, 47 FR 9987 (March 9, 1982), the following violations were identified.

- A. 10 CFR 20.207(a) requires that licensed materials stored in an unrestricted area shall be secured from unauthorized removal from the place of storage.

Contrary to the above, the requirement to secure licensed material from unauthorized removal was not met in that drums of radioactive waste were stored in a fenced area behind Building A with no means of security to prevent unauthorized removal through an open gate during normal working hours.

This is a Severity Level V Violation (Supplement VI).

- B. License Condition 18 requires that licensed material be used in accordance with statements and procedures contained in your application dated June 20, 1980. One procedure in your application requires that laboratory areas be surveyed for contamination at monthly intervals.

Contrary to the above, several laboratories in Building G had not been surveyed for contamination at monthly intervals.

This is a Severity Level V Violation (Supplement VI).

Pursuant to the provisions of 10 CFR 2.201, you are hereby required to submit to this office within thirty days of the date of this Notice, a written statement or explanation in reply, including: (1) admission or denial of the alleged violations; (2) the reasons for the violations if admitted; (3) the corrective steps which have been taken and the results achieved; (4) corrective steps which will be taken to avoid further violations; and (5) the date when full compliance will be achieved. Consideration may be given to extending your response time for good cause shown.

Date: _____