


DWIGHT D. EISENHOWER VA MEDICAL CENTER
LEAVENWORTH, KANSAS 66043



Veterans
Administration

December 6, 1993

Nuclear Regulatory Commission
Region IV
611 Ryan Plaza Drive, Suite 1000
Arlington, Texas 76011




Reply Refer To: 686/115
License: 15-08114-01

SUBJ: Response to Notice of Violation 030-01744/93-01 Dated 11/17/93

Our facility was inspected on 10/18/93, and one item was identified as being in non-compliance with the appropriate regulations. The purpose of this letter is to respond to this violation notice.

The radiation physicist failed to collect all of the appropriate data for the dose calibrator linearity test. His tests were carried out to approximately 30 uCi. The physicist has been instructed that all future dose calibrator tests must be acquired to 10 uCi or to the lowest level specified by the NRC for this particular test. A dose calibrator linearity test was acquired between 10/21/93 and 10/25/93 down to 1.7 uCi. Full compliance was achieved on that date.

If additional information is needed concerning the above information, please do not hesitate to call.


JAMES H. CUER
Medical Center Director

210075

94-0305

DMB (IE-07)

93-2230154 931206
ADOCK 03001744
PDR

America is #1—Thanks to our Veterans™

1/0