



SACRAMENTO MUNICIPAL UTILITY DISTRICT □ 6201 S Street, Box 15830, Sacramento, California 95813; (916) 452-3211

RJR 82-404

August 5, 1982

DIRECTOR
OFFICE OF INSPECTION AND ENFORCEMENT
U S NUCLEAR REGULATORY COMMISSION
WASHINGTON DC 20555

OPERATING PLANT STATUS REPORT
DOCKET NO. 50-312

Enclosed is the July, 1982 Operating Plant Status Report
for Rancho Seco Unit 1.

R. J. Rodriguez

Manager Nuclear Operations

Enclosure

cc: I&E Washington (9)
Region V
MIPC (2)

IE24

8208190265 820805
PDR ADOCK 05000312
R PDR

July 1982

SUMMARY OF PLANT OPERATIONS

The plant has been in Cold Shutdown condition the entire month for OTSG Aux. Feedwater Ring Headers repairs and modifications.

PERSONNEL CHANGES REQUIRING REPORTING

No personnel changes that require reporting in accordance with Technical Specification Figure 6.2-2 were made in July, 1982.

SUMMARY OF CHANGES IN ACCORDANCE WITH 10 CFR 50.59 (b)

Replacement of Turbine LP-1 rotor with a refurbished rotor having six discs that are of a different design from the original. See attachment.

MAJOR ITEMS OF SAFETY RELATED MAINTENANCE

1. Continued repair and modification of A & B OTSG Aux. Feedwater Headers.