



August 12, 1982

PNS-LI-82-339

Mr. James P. O'Reilly
Regional Administrator, Region II
U.S. Nuclear Regulatory Commission
101 Marietta Street, Suite 3100
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

REPORTABLE OCCURRENCE 250-82-11
TURKEY POINT UNIT 3
DATE OF OCCURRENCE: JULY 13, 1982
TECHNICAL SPECIFICATION 4.0.1
MISSED SURVEILLANCE

The attached Licensee Event Report is being submitted in accordance with Technical Specification 6.9 to provide 30 day notification of the subject occurrence.

Very truly yours,

A handwritten signature in cursive script, appearing to read "J.W. Williams, Jr.", is written over the typed name.

J.W. Williams, Jr.
Vice President
Nuclear Energy

PLP/mbd

Attachment

cc: Director, Office of Inspection and Enforcement (30)
Harold F. Reis, Esquire
File 933.1 TP

OFFICIAL COPY

Handwritten initials "TE22" in a stylized, cursive script.

8208200115 820812
PDR ADOCK 05000250
S PDR