

AUG 13 1982

30-2194
30-842
30-17842

University of Minnesota
ATTN: Dr. Peter McGrath
President
W-168 Boynton Health Service
410 Church Street South East
Minneapolis, MN 55455

License No. 22-00218-29
License No. 22-00187-46
License No. 22-00187-51

Gentlemen:

This refers to the routine safety inspection conducted by Mr. C. T. Oberg of this office on July 26 through 30, 1982, of activities authorized by NRC Byproduct Material Licenses No. 22-00218-29, No. 22-00187-46 and No. 22-00187-51 and to the discussion of our findings with Dr. D. Vestley, Director of Environmental Health and Safety Department, Dr. M. Meyer, Committee Chairman, Mr. R. O. Wollen, and others of your staff at the conclusion of the inspection.

The inspection was an examination of activities conducted under your license as they relate to radiation safety and to compliance with the Commission's rules and regulations and with the conditions of your license. The inspection consisted of a selective examination of procedures and representative records, observations, independent measurements, and interviews with personnel.

In addition to the above areas, the inspector examined actions described in your letters dated July 15 and 16, 1980, regarding apparent items of noncompliance found during our April and May 1980 inspection. We have no further questions regarding these matters.

No items of noncompliance with NRC requirements were identified during the course of this inspection.

We will gladly discuss any questions you have concerning this inspection.

Sincerely,

D. G. Wiedeman, Chief
Materials Radiation Protection
Section 1

cc: Dr. D. Vestley
Dr. M. Meyer
Dr. J. Gander
Mr. R. O. Wollen
Mr. J. A. Staiger
DMB/Document Control Desk (RIDS)

RIII
Oberg/jp
8/12/82

RIII
Wiedeman
8/13/82

RIII
Miller
8/13/82

IE HQ FILE COPY

8208200181 820813
NMS LIC30
22-00218-29 PDR

DMB IE-07