
50-344



Portland General Electric Company Trojan Nuclear Plant P.O. Box 439 Rainier, Oregon 97048 (503) 556-3713 6 PN 12 S 2

August 12, 1982 CPY-649-82

Mr. R. H. Engelken Regional Administrator US Nuclear Regulatory Commission 1450 Maria Lane - Suite 210 Walnut Creek, California 94596-5368

Dear Sir.

In reference to our letters dated June 15, 1982 to R. H. Engelken (CPY-465-82) and July 20, 1982 to R. H. Engelken (CPY-580-82) concerning the nonoperability of certain seismic monitoring equipment, SR-6340, Bottom of Containment Triaxial Peak Accelerograph and SR-6341, Containment Foundation Triaxial Response-Spectrum Recorder, have been returned to service. ST-6336, the Triaxial Time-History Recording Accelerograph system, has been replaced with new equipment from a different manufacturer and is installed. This new equipment has not been calibrated on site yet due to lack of special calibration equipment, procedures and training. The vendor is scheduled to be on site August 14 and 15 to calibrate the trigger and accelerographs, and return the week of August 30 to calibrate the electronics in the Control Room.

Based on the above information it is estimated that the Triaxial Time-History Recording Accelerograph will be returned to service by September 10, 1982.

Sincerely. fundt

C. P. Yundt General Manager

CPY/DWS/DLB:mlf

c: LER Distribution File 93.24a(Q)

8208200184

IE-29